



April 2015

To whom it may concern;

The City of Toronto recently experienced a leak in the cold brine floor at Ryerson outdoor rink. The facility was losing ~80 gallons of brine a day. To make matters worse the leak was somewhere in the concrete slab making a repair more intrusive and costly to repair.

After consulting with our refrigeration service provider we decided to try using the Rink Seal Pro instead of cutting and patching the floor.

We added the product to our system and the brine level held steady almost immediately. We were able to operate the remainder of the season without any further floor issues. The Rink Seal Pro solution proved to be a very cost effective solution to our floor leak problem.

I would not hesitate to recommend this product to anyone experiencing a leak in their rink floor.

Regards,

A handwritten signature in blue ink, appearing to read "Dave Dermott". The signature is stylized and fluid.

Dave Dermott  
City of Toronto